Mar 26 2019 11:24:01-PM

VIN retrieved from vehicle

VIN: 3HGGK5G51FM784803

- 1 Antilock Braking System Trouble Codes:
 - C0051-62:
- 1 Supplemental Restraint System Trouble Codes:
 - U0101-00: Lost Communication With Transmission Control Module (TCM) : No Sub Type Information

Disclaimer:

This information is provided without warranty and is subject to the Terms of Use posted at <u>www.lemurmonitors.com/eula.html</u>. Reproduction of this information or any portion thereof constitutes infringement of copyright.

